

RENATURATION DU RUISSEAU DE SAINT-OUEN

Localisation : En amont de la rue Clément Ader et de l'étang communal.



Problématique du site : Le gabarit du cours d'eau était bien trop large, ce qui provoquait un envasement et des faibles vitesses.

Descriptif des travaux et technique utilisée :

Le chantier s'est réalisé en partenariat avec le lycée agricole d'Areines-Vendôme, les élèves ont participé à la rédaction de la demande au titre de la loi sur l'eau ainsi qu'à la mise en place des pierres dans le cours d'eau.

Période de travaux : Mai 2019

Présentation des bénéfices observés : Le cours d'eau présente maintenant différents faciès d'écoulements, des zones rapides et d'autres plus lentes. On peut observer la présence de différents poissons.

Maître d'ouvrage : Communauté d'Agglomération Territoires vendômois (CATV)

Partenaires financiers de l'opération :

Agence de l'Eau Loire Bretagne (60%) – Région Centre-Val de Loire (20%)

 A group of construction workers wearing yellow vests and hard hats are gathered at the edge of a river. They appear to be preparing materials or equipment for the renovation work. In the background, there are houses and trees.	 A view of the riverbed after the renovation. The channel has been narrowed and deepened, with a bed of stones and gravel. The water is flowing more rapidly than before. Some workers are visible in the background near the newly constructed bank.
Tronçon amont avant travaux	Tronçon amont après travaux